

# Inspection Photos

API: 043-40001

Operator: JAVERNICK OIL

Inspection Date: 11/8/2023



## Inspection Photos



**Photo 1.** Facing north along the access road. A recent storm event has created an erosion gully along the roadside which needs to be repaired.





## Inspection Photos



**Photo 2.** Facing back south toward the erosion gully along the roadside which needs to be repaired. A 4.5 ft. shovel shows depth of erosion.





## Inspection Photos



**Photo 3.** The culvert at this drainage crossing has filled in with sediment and debris and must be cleaned out.





## Inspection Photos



**Photo 4.** Facing northeast toward the abandoned wellsite which was never reclaimed. Soils remain bare of vegetation. Previous corrective action was not completed.



## Inspection Photos



**Photo 5.** There is a cement block and guy line anchor that remains at the east side of the location that needs to be removed.





## Inspection Photos



**Photo 6.** Facing northeast at the wellsite. There is a metal cable guyline anchor that remains at red arrow.

