

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/06/2023

Submitted Date:

11/07/2023

Document Number:

702502102

FIELD INSPECTION FORM

 Loc ID: 313094
 Inspector Name: Burchett, Kirby
 On-Site Inspection:
 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 10428
 Name of Operator: DIVERSIFIED ENERGY LLC
 Address: 19501 E MAIN STREET #200
 City: PARKER State: CO Zip: 80138
Findings:

- 15 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Neidel, Kris	(970) 846-5097	kris.neidel@state.co.os	
Haack, Jason	(303) 995-0826	jhaack@oagproduction.com	
Haack, Denise	(303) 507-7437	dhaack@oagproduction.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223587	WELL	SI	10/01/2022	OW	081-06954	BINGMAN 1-14	SI
285519	PIT	AC	07/07/2006		-	BINGMAN 1-14	AC

General Comment:[ECMC Inspection Report Summary](#)

On Monday, 11/06/2023, Inspector Kirby Burchett, conducted a follow up field inspection at Diversified Energy LLC on the Bingman 1-14, Location #313094, in Moffat County, Colorado.

This location is within or in close proximity to a CPW District with High Priority, NSO, Density and Other Consultation Habitat Regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Inspection # 702501403 on 6/1/23. Corrective Actions that not have been resolved will retain the original due date.

Compliance issues observed on 6/1/23 that are still unresolved include:

1. Random debris.
2. Open end loadlines.
3. Tank battery sign missing required information.
4. Insufficient Stormwater BMPs.

Refer to Inspection Photos for observed compliance issues.

While there during normal operations the following compliance issue was also observed:

1. Fence not maintained around pit.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	As Location Entrance signs are replaced: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available) will be required.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Sign at tank battery missing information.		
Corrective Action:	The Tank battery sign will be no less than 3 square feet and no more than 6 square feet, and will provide: Name of the Operator; Telephone number at which the Operator can be reached at all times; Telephone number for local emergency services (911 where available); The public road used to access the Tank battery site; Well name(s) and API number(s) associated with the Tank battery and the legal location of the Well(s); and Location, including the quarter/quarter section, of the Tank battery.	Date:	08/01/2023
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	303-995-0826 or 911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	All excess materials, rubbish, supplies, trash, or other waste material will be properly contained until removed from the Oil and Gas Location. At no time will debris be placed or remain on the ground.	Date:	06/09/2023
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PIT		
Comment:	Livestock and barbed wire.		
Corrective Action:		Date:	
Equipment:			corrective date
Type: Deadman # & Marked	# 3		

Comment:		Date:	
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Propane tank	Date:	
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:		Date:	
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:		Date:	
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	Unlined			
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:	Loadline capped with rubber cap and a hose clamp. Loadlines need a secure secondary barrier to prevent spills.				
Corrective Action:	All loadline valves or tank valves that can be used as a loadline will be securely capped or plugged.				Date: 06/07/2023

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	Unlined			

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 223587 Type: WELL API Number: 081-06954 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last Production - September 2022
Production Reports - August 2023

Corrective Action: _____ Date: _____

Facility ID: 285519 Type: PIT API Number: - Status: AC Insp. Status: AC

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Stormwater BMPs need implementation and maintenance](#)

Corrective Action: **Provide proper Stormwater BMPs to control runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. Vehicle tracking BMPs to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.**

Date: 06/17/2023

Pits: NO SURFACE INDICATION OF PIT

Type: Evaporation Lined: NO Pit ID: 285519 Lat: 40.389080 Long: -108.136300

Reference Point: _____ Other: _____ Length: 140 Width: 50

Lining:

Liner Type: _____ Liner Condition: _____

Comment: [Unlined](#)

Corrective Action

Date:

Fencing:

Fencing Type: Livestock Fencing Condition: Inadequate

Comment: [Fence not maintained](#)

Corrective Action

Fence is down allowing livestock to enter

Date: 11/17/2023

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date:

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment: [Evap pit not in use. No treating equipment on location.](#)

Corrective Action

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403588371	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6314458
702502103	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6314457