

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/07/2023

Submitted Date:

11/07/2023

Document Number:

701007620**FIELD INSPECTION FORM**Loc ID 318187 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections
Revas, Robbie		robbie.revas@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240815	WELL	PR	08/01/2023	OW	123-08603	MARIE GERHARDT B 4	PR

General Comment:[Routine Inspection](#)

Location				
Lease Road:				
Type	Access			
comment:	Access wellhead from residential road			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Lease sign laying on the ground by wellhead. Sign is faded and doesn't have all required information			
Corrective Action:	Install sign to comply with Rule 605.d.			Date: 12/07/2023
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Wire fence around wellhead and concrete pads			
Corrective Action:				Date:
Equipment:				
Type: Bradenhead	# 1			corrective date
Comment:	Bradenhead plumbed to surface on south side of wellhead			
Corrective Action:				Date:
Type: Plunger Lift	# 0			
Comment:	Plunger lift has been removed and converted to conventional lift			
Corrective Action:				Date:
Type: Deadman # & Marked	# 4			
Comment:	All deadmen are marked			
Corrective Action:				Date:
Type: Ancillary equipment	# 0			
Comment:				
Corrective Action:				Date:
Venting:				
Yes/No				
Comment:				

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	240815	Type:	WELL	API Number:	123-08603	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift has been removed and converted. Polished rod and stuffing box have been installed at time of inspection								
Corrective Action:								Date:	

--	--	--	--	--	--	--	--	--	--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					

Comment: [Crushed concrete and asphalt have been added south of wellhead for heavy equipment mobility](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403588420	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6314577
701007624	location photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6314574