

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/06/2023

Submitted Date:

11/07/2023

Document Number:

712700835**FIELD INSPECTION FORM**Loc ID 313563 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10506Name of Operator: SEELEY OIL COMPANY LLCAddress: PO BOX 1058City: CORTEZ State: CO Zip: 81321**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Seeley, Nathaniel	(970) 565-2136	nathaniel@seeleyoil.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224487	WELL	SI	12/01/2021	OW	083-06552	CUTTHROAT 9	SI

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

Location			
Lease Road:			
Type	Access		
comment:	Long access across private land. Locked gate, Seeley combo. Dirt surfaced.		
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Metal sign posted at location entrance.		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Lube oil label not legible.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Warning signs on pumpjack. Warning signs on separator.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	24 hour operator contact number and 911 local emergency number posted on well location signage.		
Corrective Action:			Date:
Good Housekeeping:			
Type	OTHER		
Comment:	Location recently dragged.		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type			
Comment:			
Corrective Action:			Date:
Equipment:			
Type: Prime Mover	# 1		corrective date
Comment:	Natural gas motor		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:	On separator vent stack.		

Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Lube oil container.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	Entire containment berm is weathered and eroded. See photos #7-#8.		
Corrective Action:	Repair or install berms or other secondary containment devices.	Date:	12/07/2023
Type: Flow Line	# 3		
Comment:	2-3" line from wellhead to separator. 1-1" line from separator to prime mover.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 224487 Type: WELL API Number: 083-06552 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: EQUIPMENT ONSITEComment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 11/29/2022Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass	Compaction				
Compaction	Pass					
Berms	Pass	Culverts	Pass	Material Handling And Spill Prevention	Fail	Lube oil container has no spill prevention.
Drains	Pass	Ditches	Pass			

Comment: [Lube oil container with no spill prevention.](#)
[No visible erosion or sediment migration observed during inspection.](#)

Corrective Action: [Implement spill prevention per Rule 1002.f.\(2\)B.](#)

Date: 11/22/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403587027	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6313305
712700841	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6313297