

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/06/2023

Submitted Date:

11/07/2023

Document Number:

712700838**FIELD INSPECTION FORM**Loc ID 313539 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10506Name of Operator: SEELEY OIL COMPANY LLCAddress: PO BOX 1058City: CORTEZ State: CO Zip: 81321**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Seeley, Nathaniel	(970) 565-2136	nathaniel@seeleyoil.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224392	WELL	TA	04/01/2023	OW	083-06457	CUTTHROAT 4	TA

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

Location					
Lease Road:					
Type	Access				
comment:	Access from CR Y. Long, rough, rock surfaced in areas, majority dirt surfaced. Two locked gates, Seeley combos.				
Corrective Action	L				Date:
Overall Good: <input checked="" type="checkbox"/>					
Signs/Marker:					
Type	WELLHEAD				
Comment:	Metal sign posted at location entrance.				
Corrective Action:					Date:
Emergency Contact Number:					
Comment:	24 hour operator contact number and 911 local emergency number posted on well location signage.				
Corrective Action:					Date:
Good Housekeeping:					
Type	WEEDS				
Comment:	Location is overgrown with rabbitbrush, sunflower, Russian thistle, and musk thistle.				
Corrective Action:	Control weeds throughout location per Rule 606.				Date: 11/22/2023
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment: <input type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type					
Comment:					
Corrective Action:					Date:
Equipment:					
Type: Bird Protectors	# 1				corrective date
Comment:	On separator vent stack.				
Corrective Action:					Date:
Type: Flow Line	# 4				
Comment:	3-3" lines, 1-2" lines, protruding from ground.				
Corrective Action:					Date:
Type: Ancillary equipment	# 1				
Comment:	Wellhead				
Corrective Action:					Date:
Type: Horizontal Heated Separator	# 1				
Comment:	Observed impacted material on ground at separator. See photo #7.				

Corrective Action:	Conduct maintenance on equipment, cleanup stained material and increase self-inspection intervals.		Date:	11/22/2023
Type: Flow Line	# 2			
Comment:	2-2" lines from separator into the ground. No lines connected to wellhead.			
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	Meterhouse.			
Corrective Action:			Date:	
Type: Gathering Line	# 1			
Comment:	Above ground valve			
Corrective Action:			Date:	
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:			Date:	
Type: Bradenhead	# 1			
Comment:	Accessible			
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 224392 Type: WELL API Number: 083-06457 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Corrective Action: Date: _____**BradenHead**Date of Last Brhd Test: 11/29/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0Comment: Corrective Action: Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Ditches	Pass			
Gravel	Pass	Gravel	Pass			
Berms	Pass	Culverts	Pass			

Comment: No visible erosion or sediment migration observed during inspection.Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403587031	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6313307
712700842	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6313301