

Morningstar Gallegos 32-5 19-2: Location ID/API #:007-06219



Photo #1 View of the posted well location signage.

Morningstar Gallegos 32-5 19-2: Location ID/API #:007-06219



Photo #2 View of the Gallegos 9-2 wellhead assembly.

Morningstar Gallegos 32-5 19-2: Location ID/API #:007-06219



Morningstar Gallegos 32-5 19-2: Location ID/API #:007-06219




Morningstar Gallegos 32-5 19-2: Location ID/API #:007-06219



Photo #5 View of the Candelaria 20-2 wellhead assembly.

Morningstar Gallegos 32-5 19-2: Location ID/API #:007-06219



Morningstar Gallegos 32-5 19-2: Location ID/API #:007-06219



Photo #7 View of the posted well location signage.

Morningstar Gallegos 32-5 19-2: Location ID/API #:007-06219



Morningstar Gallegos 32-5 19-2: Location ID/API #:007-06219



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo #9 View of the Gallegos 19-4 pumpjack.

Morningstar Gallegos 32-5 19-2: Location ID/API #:007-06219



Photo #10 View of weeds growing in tank berm.

Morningstar Gallegos 32-5 19-2: Location ID/API #:007-06219



Photo #11 View of separation equipment.

Morningstar Gallegos 32-5 19-2: Location ID/API #:007-06219



Morningstar Gallegos 32-5 19-2: Location ID/API #:007-06219



Morningstar Gallegos 32-5 19-2: Location ID/API #:007-06219



Photo #14 Overview of the well location, west view.

Morningstar Gallegos 32-5 19-2: Location ID/API #:007-06219



Morningstar Gallegos 32-5 19-2: Location ID/API #:007-06219




Photo #16 Overview of the well location, north side.

Morningstar Gallegos 32-5 19-2: Location ID/API #:007-06219



Photo #17 Overview of the well location, west view.

Morningstar Gallegos 32-5 19-2: Location ID/API #:007-06219

