

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/13/2023

Submitted Date:

11/14/2023

Document Number:

712700866**FIELD INSPECTION FORM**Loc ID 333341 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10755Name of Operator: MORNINGSTAR OPERATING LLCAddress: 400 W 7TH STCity: FORT WORTH State: TX Zip: 76102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 317 | WELL | PR | 02/06/2008 | CBM | 007-06244 | GALLEGOS 32-5 19-4 | PR |
| 288282 | WELL | PR | 04/10/2008 | CBM | 007-06231 | CANDELARIA 32-5 20-2 | PR |

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.
There are three producing wells located together on this large location.

Equipment inventory listed on Gallegos 32-5 19-2, (007-06219), FIR Doc.#712700865.

| Location | | | | |
|--|---|--------|--|------------------|
| Lease Road: | | | | |
| Type | Access | | | |
| comment: | Access from CR 975, locked gate, Morningstar combo. Gravel surface. | | | |
| Corrective Action | L | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | | |
| Signs/Marker: | | | | |
| Type | CONTAINERS | | | |
| Comment: | Content and volume label. | | | |
| Corrective Action: | | | | Date: |
| Type | TANK LABELS/PLACARDS | | | |
| Comment: | Content and volume label, NFPA placard on produced water tanks. | | | |
| Corrective Action: | | | | Date: |
| Type | WELLHEAD | | | |
| Comment: | Metal sign posted on pumpjack fencing. | | | |
| Corrective Action: | | | | Date: |
| Type | OTHER | | | |
| Comment: | Warning signs on pumpjacks and fenced enclosures. | | | |
| Corrective Action: | | | | Date: |
| Emergency Contact Number: | | | | |
| Comment: | 24 hour operator contact number and 911 local emergency number posted on well location signage. | | | |
| Corrective Action: | | | | Date: |
| Good Housekeeping: | | | | |
| Type | WEEDS | | | |
| Comment: | Weeds growing around Candelaria 20-2 wellhead and within produced tank berm. | | | |
| Corrective Action: | Control weeds across location per Rule 606. | | | Date: 11/29/2023 |
| Overall Good: <input checked="" type="checkbox"/> | | | | |
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: <input type="text"/> | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |
| Fencing/: | | | | |
| Type | TANK BATTERY | | | |
| Comment: | Pipe rail and hog wire. | | | |
| Corrective Action: | | | | Date: |
| Venting: | | | | |
| Yes/No | NO | | | |
| Comment: | | | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected FacilitiesFacility ID: 317 Type: WELL API Number: 007-06244 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: Fluid Type: End Surf Csg Pressure: Comment: Corrective Action: Date: Facility ID: 288282 Type: WELL API Number: 007-06231 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: Fluid Type: End Surf Csg Pressure: Comment: Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|-------------------------------|
| Gravel | Pass | Gravel | Pass | | | |
| Compaction | Pass | Culverts | Pass | Material Handling And Spill Prevention | Pass | Container within containment. |
| Ditches | Pass | Ditches | Pass | | | |

Comment: [No visible erosion or sediment migration observed during inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 712700875 | INSPECTION PHOTOS | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6321296 |