

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/06/2023

Submitted Date:

11/13/2023

Document Number:

709200021

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: _____ On-Site Inspection
 320003 _____ Abrams, Deborah _____ 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 10711
 Name of Operator: PAINTED PEGASUS PETROLEUM LLC
 Address: 16820 BARKER SPRINGS RD #521
 City: HOUSTON State: TX Zip: 77084
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments
 0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|----------------------------|---------|
| Hickey, Mike | | michael.hickey@state.co.us | |

General Comment:

This is an orphaned well inspection. Inspection completed to document current condition of location, equipment, and wellhead. Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program. See link at end of report for path to downloadable documents and pictures.

The tank battery is located 200' E of the wellhead, sharing the same Location ID.

Wellhead is not fenced. No livestock observed.

Wellhead checked with soapy solution, bubbles were observed. Audible leak. See attached photo and video.

Attached files have Trimble GPS screenshot for the located surface casing.

Location is fairly level and well head is buried in weeds on three sides.

COGCC Comments

| Comment | User | Date |
|--|---------|------------|
| This is an orphaned well inspection. Inspection completed to document current condition of location, equipment, and wellhead. Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program. See link at end of report for path to downloadable documents and pictures. The tank battery is located 200' E of the wellhead, sharing the same Location ID. Wellhead is not fenced. No livestock observed. Wellhead checked with soapy solution, bubbles were observed. Audible leak. See attached photo and video. Attached files have Trimble GPS screenshot for the located surface casing. Location is fairly level and well head is surrounded by weeds on three sides. | abramsd | 11/13/2023 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--|---|
| 709200022 | Antelope Farms 41-23 2 Inspection Photos & GPS coordinates PPT | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6321300 |
| 709200023 | Bubbling soapy solution video #1 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6321301 |

| | | |
|-----------|--|---|
| 709200024 | Bubbling soapy solution video #2 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6321302 |
| 709200028 | Antelope Farms 41-23 2 Inspection Photos & GPS coordinates PDF | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6321303 |