

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/13/2023

Submitted Date:

11/14/2023

Document Number:

712700868

FIELD INSPECTION FORMLoc ID 320844 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

19 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205209	WELL	PR	05/01/1996	CBM	007-06086	ROSS 1	PR

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

Location				
Lease Road:				
Type	Access			
comment:	Access from Lopez Road, locked gate, 2C40 key.			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Metal sign posted at location entrance on meterhouse fencing.			
Corrective Action:				Date:
Type	OTHER			
Comment:	NFPA placard on meterhouse.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	24 hour operator contact number and 911 local emergency number posted on well location signage.			
Corrective Action:				Date:
Good Housekeeping:				
Type	WEEDS			
Comment:	Rabbitbrush and kochia encroaching across location.			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	LOCATION			
Comment:	T-post and barbed wire on three sides of location.			
Corrective Action:				Date:
Type	SEPARATOR			
Comment:	Cattle panel around separator.			
Corrective Action:				Date:
Type	OTHER			
Comment:	Cattle panel around meterhouse.			
Corrective Action:				Date:
Type	OTHER			
Comment:	Cattle panel around telemetry.			
Corrective Action:				Date:

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment: Wellhead			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment: Electric motor.			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment: 2" line from separator to meterhouse. Calibration date 7/24/2023.			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment: Accessible			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment: Linear rod pump.			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment: Telemetry, electrical panel/service, electrical control box, cathodic protection.			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment: 3" line from wellhead to separator.			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	205209	Type:	WELL	API Number:	007-06086	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	01/13/2023		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	0	Fluid Type:						
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Berms	Pass	Culverts	Pass			
Compaction	Pass	Ditches	Pass			

Comment: No visible erosion or sediment migration observed during inspection.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700872	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6321298