


**KT Resources LLC
WRD Dow 20-13
Location ID: 316300**



As entrance signs are replaced additional information will be required



Access road to location

KT Resources LLC
WRD Dow 20-13
Location ID: 316300

[illegible]

Calibration displayed but out of compliance.

Leaking equipment. Impacted soil.

**KT Resources LLC
WRD Dow 20-13
Location ID: 316300**



Rain cap off relief valve



Venting from relief valve

**KT Resources LLC
WRD Dow 20-13
Location ID: 316300**



Stained soil



As well signs are replaced additional information will be required

**KT Resources LLC
WRD Dow 20-13
Location ID: 316300**



Location from Northeast corner



Location from Southeast corner

**KT Resources LLC
WRD Dow 20-13
Location ID: 316300**



Location from Southwest corner



Location from Northwest corner