

FORM  
INSPRev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/14/2023

Submitted Date:

11/14/2023

Document Number:

713300300

### FIELD INSPECTION FORM

Loc ID 320002 Inspector Name: Kester, Michael On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		randy.silver@state.co.us	
, KPK		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202208	WELL	SI	07/01/2023	OW	001-07613	ALBERT SACK D 2	SI

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	getting faded		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	safety guards		
Corrective Action:		Date:	
Type	OTHER		
Comment:	electric panel, metal panels		
Corrective Action:		Date:	

**Equipment:**

Type		#		corrective date
Type: Pump Jack		# 1		
Comment:				
Corrective Action:			Date:	
Type: Ancillary equipment		# 1		
Comment:	electrical disconnect panel			
Corrective Action:			Date:	
Type: Prime Mover		# 1		
Comment:	electrical motor			
Corrective Action:			Date:	
Type: Bradenhead		# 1		
Comment:				
Corrective Action:			Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 202208 Type: WELL API Number: 001-07613 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: at time of inspection well appeared to be shut in

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 05/18/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

**COGCC Comments**

Comment	User	Date
<p><a href="#">ECMC Inspection Report Summary</a>                      On Monday 11-14-2023 at approximately 11:00, I, Inspector Michael Kester, conducted an on-site follow up inspection as per Doc #699505041.                      Location: Albert Sack D 2                      Operator: KPK                      API#: 001-07613                      County: Adams                      While there, I observed well site with pumping unit.                      At time of inspection it does appear corrective actions from previous inspection have been address.                      Weather conditions: sunny and dry                      This is a summary of inspection report.</p> <p>This inspection does not nullify any orders or NOAV from the ECMC                      This is a continuing education inspection</p>	kesterm	11/14/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713300301	site pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6322301">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6322301</a>