

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/14/2023

Submitted Date:

11/14/2023

Document Number:

708902230

FIELD INSPECTION FORMLoc ID 311542 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10550

Name of Operator: MUSTANG RESOURCES LLC

Address: PO BOX 13550

City: BAKERSFIELD State: CA Zip: 93389

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
, Mustang		nwelch@vaqueroenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210684	WELL	PR	09/01/2018	GW	045-06440	WF CLOUGH FEDERAL 14-24-6S-94W	PR

General Comment:

CECMC Inspection Report Summary

On 11/14/2023 at approximately 10:21 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection at MUSTANG RESOURCES LLC WF CLOUGH FEDERAL 14-24-6S-94W

Location # 311542 in Garfield County Colorado.

Location is within High Priority/Density Habitat areas & in close proximity to Bald Eagle Roost Site.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Equipment - Gas meter not calibrated annually with a CA date of 12/14/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/888-291-8588

Corrective Action:

Date: _____

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 3		
Comment:	Marked		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible.		
Corrective Action:		Date:	
Type: Plunger Lift	# 0		
Comment:	Well not on plunger lift		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas meter not calibrated annually/calibration card at gas meter shows meter has not been calibrated since 11/24/2021 Operator (Mustang) stated the meters on all of the Clough wells are owned and operated by TEP. Operator also stated the Clough 14-24 well is commingled with the Clough 14-12 well and they share the same meter on this location. However the cal card does not have the 14-12 well listed on it.		
Corrective Action:	Operator needs to install their own meter or have TEP calibrate existing meter on location to comply with CECMC rules & update cal card.	Date:	12/14/2023

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	210684	Type:	WELL	API Number:	045-06440	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well is not on plunger lift								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
		Culverts				
		Ditches				
Gravel						Sparse to none in areas
Compaction						Light compaction in some areas
		Gravel				Sparse in sections
Berms						

Comment: Location appears to have some gravel throughout the location with light compaction. Places with sparse to no gravel are present on location. Sparse gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to Equipment for observed compliance issues.	smelserw	11/14/2023
Duel lease - Shared pad with CLOUGH FEDERAL 14-24A-6S-94W location # 311543		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708902231	Inspection 708902230 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6322325
708902232	Inspection 708902230 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6322326