

**Inspection Photos**  
**CHAMPLIN 86 AMOCO F**  
**Spill ID 482153/Remediation Project No 22276**



**Photo 1 – Backfill dirt stockpile – AM inspection.**



**Photo 2 - Backfill dirt stockpile. Backfill in process – AM inspection.**

**Inspection Photos**  
**CHAMPLIN 86 AMOCO F**  
**Spill ID 482153/Remediation Project No 22276**



**Photo 3 – Backfill in process – AM inspection.**



**Photo 4 - Backfill in process – AM inspection.**



**Inspection Photos**  
**CHAMPLIN 86 AMOCO F**  
**Spill ID 482153/Remediation Project No 22276**



**Photo 5 – Backfill in process – AM inspection.**



**Photo 6 - Backfill dirt stockpile – AM inspection.**

Inspection Photos  
CHAMPLIN 86 AMOCO F  
Spill ID 482153/Remediation Project No 22276



**Photo 7 – Backfill dirt stockpile – PM inspection.**



**Photo 8 - Backfill dirt stockpile – PM inspection.**



**Inspection Photos**  
**CHAMPLIN 86 AMOCO F**  
**Spill ID 482153/Remediation Project No 22276**



**Photo 9 – Partially backfilled excavation/weeds –  
PM inspection.**



**Photo 10 - Partially backfilled excavation/weeds –  
PM inspection.**



**Inspection Photos**  
**CHAMPLIN 86 AMOCO F**  
**Spill ID 482153/Remediation Project No 22276**



**Photo 11 – Partially backfilled excavation/weeds – PM inspection.**



**Photo 12 - Fencing – PM inspection.**