

Inspection Photos
Lawrence Totems Consolidation Line
Spill ID 477024/Remediation Project No 15811



COGCC Inspection
40.0473, -104.94222, 5017.2ft, 211°
11/13/2023 02:08:21 PM



COGCC Inspection
40.04731, -104.94226, 5026.6ft, 135°
11/13/2023 02:08:31 PM

Photo 1 – Site photo/weeds.

Photo 2 - Site photo/weeds.

Inspection Photos
Lawrence Totems Consolidation Line
Spill ID 477024/Remediation Project No 15811



COGCC Inspection
40.04721, -104.94223, 5027.2ft, 152°
11/13/2023 02:08:42 PM



COGCC Inspection
40.04712, -104.94224, 5022.5ft, 135°
11/13/2023 02:08:54 PM

Photo 3 – Weeds.

Photo 4 - Weeds/monitoring well.

Inspection Photos
Lawrence Totems Consolidation Line
Spill ID 477024/Remediation Project No 15811



COGCC Inspection
40.04709, -104.94227, 5025.2ft, 6°
11/13/2023 02:09:03 PM



COGCC Inspection
40.04711, -104.94227, 5023.7ft, 341°
11/13/2023 02:09:11 PM

Photo 5 – Site photo/weeds/excavation area.

Photo 6 - Excavation area.

Inspection Photos
Lawrence Totems Consolidation Line
Spill ID 477024/Remediation Project No 15811



COGCC Inspection
40.04717, -104.94225, 5023.5ft, 280°
11/13/2023 02:09:32 PM



COGCC Inspection
40.04717, -104.94225, 5023.3ft, 245°
11/13/2023 02:09:33 PM

Photo 7 – Excavation area.

Photo 8 - Excavation area.

Inspection Photos
Lawrence Totems Consolidation Line
Spill ID 477024/Remediation Project No 15811



COGCC Inspection
40.04725, -104.94232, 5020.3ft, 164°
11/13/2023 02:10:01 PM



COGCC Inspection
40.04723, -104.94239, 5019.3ft, 137°
11/13/2023 02:10:25 PM

Photo 9 – Excavation area.

Photo 10 - Excavation area/groundwater.

Inspection Photos
Lawrence Totems Consolidation Line
Spill ID 477024/Remediation Project No 15811



Photo 11 – Excavation area.



Photo 12 – Monitoring well.