

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2023

Submitted Date:

11/15/2023

Document Number:

697008368

FIELD INSPECTION FORMLoc ID 455319 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10177

Name of Operator: ENERPLUS RESOURCES (USA) CORPORATION

Address: 950 17TH STREET #2200

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

15 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Everhart, Jacob		jeverhart@enerplus.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
455318	WELL	AP	10/10/2022	LO	123-46985	Lethbridge 8-67-20-19	ND
455320	WELL	PR	07/08/2021	OW	123-46986	Edmonton 8-67-20-19N	PR
455321	WELL	AP	10/10/2022	LO	123-46987	Airdrie 8-67-20-19	ND
455322	WELL	AP	10/10/2022	LO	123-46988	Medicine Hat 8-67-20-19	ND
455323	WELL	AP	10/10/2022	LO	123-46989	Red Deer 8-67-20-19	ND
455324	WELL	PR	04/06/2021	OW	123-46990	St. Albert 8-67-21-22C	PR
455325	WELL	AP	10/10/2022	LO	123-46991	Calgary 8-67-21-22	ND
455326	WELL	AP	10/10/2022	LO	123-46992	Grand Prairie 8-67-21-22	ND

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	x 2		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease road entrance		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical systems		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Sign is not posted at battery.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	02/16/2024

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Flow Line	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	#		
Comment:	Automation array, chemical systems in secondary containment with wildlife protection, recirc pumps, genset, propane tank, ECD scrubbers, 100 bbl steel PRV catch tank, electrical systems		
Corrective Action:		Date:	

Type: Pump Jack	# 2		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:	Pilot is on		
Corrective Action:			Date:
Type: VRU	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Natural gas engine on genset		
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:	Calibration cards are current.		
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Flare	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 5		
Comment:	Electric motors on pump jacks, recirc pumps and VRU		
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:	Bradenhead valves are exposed at surface.		
Corrective Action:			Date:
Type: Horizontal Separator	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	6	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Lined berm			
Corrective Action:				

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			

Flaring:

Type			
Comment:			
Corrective Action:			

Inspected Facilities

Facility ID: 455318 Type: WELL API Number: 123-46985 Status: AP Insp. Status: ND

Facility ID: 455320 Type: WELL API Number: 123-46986 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 11/30/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 455321 Type: WELL API Number: 123-46987 Status: AP Insp. Status: ND

Facility ID: 455322 Type: WELL API Number: 123-46988 Status: AP Insp. Status: ND

Facility ID: 455323 Type: WELL API Number: 123-46989 Status: AP Insp. Status: ND

Facility ID: 455324 Type: WELL API Number: 123-46990 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 11/30/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: NONEEnd Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 455325 Type: WELL API Number: 123-46991 Status: AP Insp. Status: ND

Facility ID: 455326 Type: WELL API Number: 123-46992 Status: AP Insp. Status: ND

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Tracking Pad	Pass			
Gravel	Pass	Gravel	Pass	Self Inspection	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 11/15/2023 at approximately 12:20 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the Enerplus Alberta Cities East Pad location #455319 in Weld County, Colorado.</p> <p>While there, I observed that no battery sign was posted. During this inspection the following possible compliance issues were observed: Rule 605.e. with a corrective action date of 2/16/2024.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	petersont	11/15/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697008369	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6324730