

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/13/2023

Submitted Date:

11/15/2023

Document Number:

689501448

**FIELD INSPECTION FORM**

Loc ID 333171 Inspector Name: Brown, Kari On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Peterson, John		jpeterson@kpk.com	<a href="#">KPK environmental</a>
Graber, Nikki		nikki.graber@state.co.us	
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	<a href="#">all inspections.</a>
, KPK		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481067	SPILL OR RELEASE	CL	07/12/2022		-	Moser 1A	EI

**General Comment:**

[This is an environmental inspection to document backfill of Spill ID 481067/Remediation Project No 23510. Any corrective actions from previous inspections that have not been addressed are still applicable.](#)

[There were no operator or contract environmental personnel on location at the time of this field inspection.](#)

[Photos attached to document site conditions.](#)

**Inspected Facilities**

Facility ID: 481067 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: Remedial excavation for Spill ID 481067/Remediation Project No 23510 has been backfilled. The last approved Supplemental Form 27 for this remediation project was received on May 12, 2022 (Doc # 403047594). Operator is past due on quarterly reporting. This location was included in NOAV # 403513701 for violation of Rule 913.e.(3). Associated well (Moser 1A) was producing at the time of inspection. Note: Excavation was emergency backfilled to allow Operator to address wellhead integrity issues. ECMC environmental staff did not grant approval for backfill. ECMC environmental staff was not given notification for excavation backfill.

Corrective Action: Operator shall immediately submit a Form 27 for Remediation Project No 23510 with any analytical data not previously submitted and a specific workplan and timeline to address any impacts remaining in-situ. Date: 08/10/2022

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689501449	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6324719">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6324719</a>