

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/07/2023

Submitted Date:

11/09/2023

Document Number:

696305384

FIELD INSPECTION FORM

Loc ID 452726 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
452721	WELL	PR	05/24/2018	OW	123-45726	Anschutz-Williams 5-61-27-6457BSB	PR
452722	WELL	SI	08/01/2023	OW	123-45727	Anschutz-Williams 5-61-27-6457BN	SI
452724	WELL	SI	08/01/2023	OW	123-45729	Anschutz-Williams 5-61-27-4956B	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Condensate Vault West of Separators is buried by Sand, Labels no longer visible. Condensate Vault at NW Corner of Tank Berm missing Capacity Label. See photos		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	11/24/2023
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Locate Flags on location no longer valid. See photos		
Corrective Action:	Comply with Rule 606	Date:	11/24/2023
Type	DEBRIS		
Comment:	Tumbleweed Debris at Gas Meter Rack, North end of Location and in and around Tank Berm; see photos		
Corrective Action:	Comply with Rule 606	Date:	11/24/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:	Appear to be plumbed to surface		
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:			Date:
Type: LACT	# 2		
Comment:			
Corrective Action:			Date:
Type: VRU	# 4		
Comment:			
Corrective Action:			Date:
Type: VRT	# 3		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 8		
Comment:	South 2 Separators are open to Atmosphere. Appear to be down for Maintenance		
Corrective Action:	Install Temporary or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b.		Date: 11/24/2023
Type: Emission Control Device	# 3		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 8		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 2		
Comment:	Line Heaters		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	

Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment: Shares berm with the Crude Oil Tanks						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	12	400 BBLs	STEEL AST		40.365550,-104.203180	
Comment:						
Corrective Action:				Date:		
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:				Date:		
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected FacilitiesFacility ID: 452721 Type: WELL API Number: 123-45726 Status: PR Insp. Status: PR**Producing Well**Comment: PRCorrective Action: Date: Facility ID: 452722 Type: WELL API Number: 123-45727 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: Comment: SICorrective Action: Date: Facility ID: 452724 Type: WELL API Number: 123-45729 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: Comment: SICorrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap						
Ditches						
Culverts						
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Routine Field Inspection. Tumbleweed Debris throughout Location. Locate Flags on location no longer valid. South 2 Separators open to Atmosphere. Condensate Vault Labels	petrie	11/09/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403591231	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6317322
696305385	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6317315