

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2023

Submitted Date:

11/16/2023

Document Number:

712700881**FIELD INSPECTION FORM**Loc ID 325508 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:24 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214912	WELL	PR	05/06/2022	CBM	067-06516	SITTON 01-13 1	PR

General Comment:SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

Location			
Lease Road:			
Type	Access		
comment:	Access from CR 526. Gravel surface.		
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Content and volume label, NFPA placard on produced water tank.		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Label on lube oil container.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Warning signs on pumpjack enclosure.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Metal sign posted at location entrance on telemetry fencing.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	24 hour operator contact number and 911 local emergency number posted on well location signage.		
Corrective Action:			Date:
Good Housekeeping:			
Type	OTHER		
Comment:	Observed impacted material on ground at prime mover muffler. See photos #8-#9		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and increase self-inspection intervals.		Date: 11/30/2023
Type	STORAGE OF SUPL		
Comment:	Observed agricultural and recreational equipment stored/not in use on pad and on reclamation area which appears to be landowner related, no approved variance in well file. See photos #2-#3.		
Corrective Action:	Remove all unused equipment unless a variance per rule 606.a(2) is approved.		Date: 01/15/2024
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	Cattle panel enclosure around produced water tank, separator, and meterhouse.		

Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Metal mesh cage around weights and belts.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panel around wellhead assembly.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Cattle panel around telemetry.		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Wood posts and hog wire, T-posts and barbed wire on two sides of location.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 1		
Comment:	On separator vent stack.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Telemetry, cathodic protection.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead and block valve assembly.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Accessible		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Natural gas motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Lube oil container.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
----------	---	----------	------	---------	--------	--

PRODUCED WATER	1	<50 BBLs	PBV STEEL		37.218350,-107.583110	
Comment: Partially buried steel tank labled 21 bbl.						
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities									
Facility ID:	214912	Type:	WELL	API Number:	067-06516	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	05/04/2023		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	4	Fluid Type:						
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Culverts	Pass	Material Handling And Spill Prevention	Pass	Container within containment.
Gravel	Pass					
Berms	Pass	Ditches	Pass			
Compaction	Pass	Gravel	Pass			

Comment: [No visible erosion or sediment migration observed during inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700886	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6325130