

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/15/2023

Submitted Date:

11/16/2023

Document Number:

712700879

FIELD INSPECTION FORM

Loc ID 306880 Inspector Name: Pattillo, Curtis On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 25 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272399	WELL	PR	10/01/2021	CBM	067-08949	MORRISON FEDERAL 2	PR

General Comment:

[SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.](#)

Location			
Lease Road:			
Type	Access		
comment:	Access from CR 525. Private road through residences. Gravel surface.		
Corrective Action		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	NFWA placads on separator and meterhouse. Buried pipeline carsonite markers.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Warning signs on pumpjack.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Label on container.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Metal sign posted on pumpjack fencing.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Content and volume label, NFWA placard on produced water tank.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	24 hour operator contact number and 911 local emergency number posted on well location signage.		
Corrective Action:		Date:	
Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Observed irrigation pipe and fuel storage tanks stored on pad and on reclamation area which appears to be landowner related, no approved variance in well file. See photos #8 -#9.		
Corrective Action:	Remove all unused equipment unless a variance per rule 606.a(2) is approved.		Date: 01/15/2024
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	Pipe bollards around cathodic protection.		

Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panel around wellhead and pumpjack.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Cattle panel enclosure around produced water tank, separator, meterhouse, and telemetry.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Metal mesh cage around weights and belts.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 1		
Comment:	Lube oil container.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	3" line from separator to meterhouse. Calibration date 7/24/2023.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	On separator vent stack.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Telemetry, cathodic protection.		
Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:	3" line from wellhead to separator. 1" line from separator to prime mover.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	PVC access		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead and block valve assembly.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Natural gas motor.		

Corrective Action:	Date:
--------------------	-------

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	PBV STEEL		37.224850,-107.551500

Comment: Partially buried steel tank labled 95 bbl.

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate

Comment:

Corrective Action:	Date:
--------------------	-------

Venting:

Yes/No	NO			
--------	----	--	--	--

Comment:

Corrective Action:	Date:
--------------------	-------

Flaring:

Type		
------	--	--

Comment:

Corrective Action:	Date:
--------------------	-------

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			
Berms	Pass	Culverts	Pass	Material Handling And Spill Prevention	Pass	Container within containment.
Gravel	Pass					
Ditches	Pass	Ditches	Pass			

Comment: Observed gulley erosion and sediment migration on south side fill slope. See photo #8.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 11/30/2023

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700884	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6325182