

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/15/2023

Submitted Date:

11/16/2023

Document Number:

712700877

**FIELD INSPECTION FORM**

Loc ID 325626 Inspector Name: Pattillo, Curtis On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10749  
Name of Operator: SIMCOE LLC  
Address: 1199 MAIN AVE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

21 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	<a href="#">All SW Inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215122	WELL	PR	11/01/2019	CBM	067-06727	IVERS 01-16 #1	PR

**General Comment:**

[SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.](#)

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Access from CR 525, private road. Location gated, not locked. Gravel surface.		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Warning signs on pumpjack, warning signs and NFPA placard on separator.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Buried pipeline carsonite markers.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Metal sign posted at location entrance.		
Corrective Action:		Date:	
<b>Emergency Contact Number:</b>			
Comment:	24 hour operator contact number and 911 local emergency number posted on well location signage.		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	LOCATION		
Comment:	T-post, hog wire and smooth wire.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panel around wellhead and pumpjack.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Cattle panel around telemetry.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Metal mesh cage around weights and belts.		
Corrective Action:		Date:	
Type	SEPARATOR		

Comment:	Cattle panel around unitized separator/meter.			
Corrective Action:			Date:	
<b>Equipment:</b>				corrective date
Type: Vertical Heated Separator	# 1			
Comment:				
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:	Unitized within separator shack. Calibration date 8/23/2023.			
Corrective Action:			Date:	
Type: Flow Line	# 1			
Comment:	3" line from wellhead to separator.			
Corrective Action:			Date:	
Type: Bradenhead	# 1			
Comment:	PVC access			
Corrective Action:			Date:	
Type: Gathering Line	# 1			
Comment:	Buried valve can.			
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:				
Corrective Action:			Date:	
Type: Prime Mover	# 1			
Comment:	Electric motor			
Corrective Action:			Date:	
Type: Ancillary equipment	# 4			
Comment:	Telemetry, electrical service panel/control boxes, cathodic protection.			
Corrective Action:			Date:	
Type: Bird Protectors	# 1			
Comment:	On separator vent stack.			
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	Wellhead			
Corrective Action:			Date:	
Type: Deadman # & Marked	# 1			
Comment:				
Corrective Action:			Date:	

<b>Venting:</b>				
Yes/No	NO			
Comment:				
Corrective Action:			Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 215122 Type: WELL API Number: 067-06727 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 04/18/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Ditches	Pass			
Ditches	Pass	Culverts	Pass			
Gravel	Pass	Gravel	Pass			

Comment: [Gulley erosion begining around separator. See photo #5.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700882	INSPECTION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6325179">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6325179</a>