

**Inspection Photos**  
**Location Name: Razor 29H PAD**  
**Location ID: 439542**



**Photo 1 – Compressor**



**Photo 2 – Wildlife Netting missing**



**Inspection Photos**  
**Location Name: Razor 29H PAD**  
**Location ID: 439542**



**Photo 3 – Location Overview**



**Photo 4 – Location Overview**



**Inspection Photos**  
**Location Name: Razor 29H PAD**  
**Location ID: 439542**



**Photo 5 – Razor 29H-2016 Wellsite**




**Photo 6 – Razor 29H-2016 – PA'd – Cut and Capped**



**Inspection Photos**  
**Location Name: Razor 29H PAD**  
**Location ID: 439542**



**Photo 7 – Wellheads**



**Photo 8 – 29H-3212 Wellhead**

**Inspection Photos**  
**Location Name: Razor 29H PAD**  
**Location ID: 439542**



**Photo 9 – Overview**



**Photo 10 – Water LACTS**



**Inspection Photos**  
**Location Name: Razor 29H PAD**  
**Location ID: 439542**



**Photo 11 – Flare**



**Photo 12 – LACTS and Electrical Panels**

**Inspection Photos**  
**Location Name: Razor 29H PAD**  
**Location ID: 439542**



Energy and Carbon Management Commission  
40.81074, -103.88432, 4717.8ft  
11/14/2023 14:10:36

**Photo 13 – Overview**



Energy and Carbon Management Commission  
40.81067, -103.88429, 4718.7ft  
11/14/2023 14:10:44

**Photo 14 – Bulk Tanks**



**Inspection Photos**  
**Location Name: Razor 29H PAD**  
**Location ID: 439542**



**Photo 15 – Overview**



**Photo 16 – Overview**



**Inspection Photos**  
**Location Name: Razor 29H PAD**  
**Location ID: 439542**



**Photo 17 – Overview**



**Photo 18 – Compressor**