

Inspection Photos

11/14/2023

Operator: CAERUS PICEANCE LLC

Location ID: 485123 / 485124

Inspection Doc: 696205419

Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC
Location ID: 485123 / 485124



Photo 1: Signage at the Location entrance.



Inspection Photos

Operator Name: CAERUS PICEANCE LLC

Location ID: 485123 / 485124



Photo 2: Photos examples showing erosion logs implemented to manage runoff/runoff, and stormwater sediment transport.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC
Location ID: 485123 / 485124



Photo 3: Photo example showing area where soils have been pushed over the erosion logs during construction.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC

Location ID: 485123 / 485124



Photo 4: Photo example of slopes along the Location that will require additional stabilization control measures. Soils at risk to wind and water erosion; fugitive dust control measures required.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC

Location ID: 485123 / 485124



Photo 5: Photos examples showing topsoil salvaged along the access road. Soils currently loose and at risk to wind and water erosion; fugitive dust issues observed at time of inspection.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Section Photos

Client: CAERUS PICEANCE LLC

Section ID: 485123 / 485124



39.95266494N 108.27890988W
November 14, 2023

November 14, 2023

Photo 6: Soil test pit conducted within the “drainage” section of the access road. Topsoil depth at pit determined to be 6 inches.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC

Location ID: 485123 / 485124



Photo 7: Photos 7-12 taken with use of a sUAS. Photos provide aerial views of the access road construction in process.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC

Location ID: 485123 / 485124



Photo 8: See comments under photo 7.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC

Location ID: 485123 / 485124



Photo 9: See comments under photo 7.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC
Location ID: 485123 / 485124



Photo 10: See comments under photo 7.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC

Location ID: 485123 / 485124



Photo 11: See comments under photo 7. Photo shows the access road leading to the proposed PCU Fed #B27-197 Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC

Location ID: 485123 / 485124



Photo 12: See comments under photo 7. Photo shows the access road leading to the proposed PCU Fed #A27-197 CDP Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources