

# Inspection Photos

Loc: 309208

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 11/14/2023

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northwest along the access road that remains per approved variance.





## Inspection Photos



**Photo 2.** Facing northwest further along the access road which is stabilized with BMP's.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:309208 | Date: 11/14/2023



## Inspection Photos



**Photo 3.** Facing northwest along the access road. There is erosion occurring along this area ascending to the location and will need to be repaired.





## Inspection Photos



**Photo 4.** Facing northwest toward the location that remains per approved variance.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:309208 | Date: 11/14/2023



## Inspection Photos



**Photo 5.** Facing along the fill slope of the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:309208 | Date: 11/14/2023



## Inspection Photos



**Photo 6.** There are a few noxious weeds along the fill slope that will need to be controlled. Red arrow points to Musk thistle rosettes.





## Inspection Photos



**Photo 7.** Facing northwest toward the cut slope.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:309208 | Date: 11/14/2023



## Inspection Photos



**Photo 8.** Facing northeast at the location. This area appears to have been reseeded but has not yet established vegetation.





## Inspection Photos



**Photo 9.** Facing northwest at the east cut slope. There is erosion along this area of the cut slope which is not yet stabilized.

