

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/16/2023

Submitted Date:

11/17/2023

Document Number:

712700890

FIELD INSPECTION FORM

Loc ID 306873 Inspector Name: Pattillo, Curtis On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271492	WELL	PR	08/01/2018	CBM	067-08931	LE PLATT B 1	PR

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a follow up field inspection to verify completion of corrective actions identified in FIR Document #712700747 submitted 10/17/2023. Corrective action identified is ongoing and unresolved.

A FIRR was submitted 11/9/2023, Doc.#403590422.

Equipment inventory listed on previous inspection, no change to location equipment.

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	Warning signs on pumpjack enclosure.		
Corrective Action:		Date:	
Type			
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Metal sign posted at location entrance.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

Good Housekeeping:

Type	OTHER		
Comment:	Observed impacted material on ground at prime mover muffler. See photos #2, #4. This corrective action was identified in FIR Doc.#712700747, submitted 10/17/2023. A FIRR was submitted 11/9/2023, Doc.#403590422.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and increase self-inspection intervals.	Date:	12/04/2023

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 271492 Type: WELL API Number: 067-08931 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 07/11/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Ditches	Pass			
Berms	Pass	Culverts	Pass	Material Handling And Spill Prevention	Pass	Container within containment.
Gravel	Pass					
Ditches	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700895	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6326954