

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/16/2023

Submitted Date:

11/17/2023

Document Number:

712700889

**FIELD INSPECTION FORM**

Loc ID 306860 Inspector Name: Pattillo, Curtis On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10749  
Name of Operator: SIMCOE LLC  
Address: 1199 MAIN AVE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Findings:**

8 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name     | Phone | Email                         | Comment            |
|------------------|-------|-------------------------------|--------------------|
| Labowskie, Steve |       | steve.labowskie@state.co.us   |                    |
| , General        |       | sjninspections@ikavenergy.com | All SW Inspections |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name    | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 270212      | WELL | PR     | 05/18/2004  | CBM        | 067-08897 | EVELYN PAYNE E 2 | PR          |

**General Comment:**

SW Compliance Specialist Curtis Pattillo conducted a follow up field inspection to verify completion of corrective actions identified in FIR Document #712700749. Corrective actions identified have been completed.

Equipment inventory is listed on previous inspections, no change to location equipment.

**Location**

Overall Good:

**Signs/Marker:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               | WELLHEAD                                   |       |  |
| Comment:           | Metal sign posted at location entrance.    |       |  |
| Corrective Action: |  | Date: |  |
| Type               | OTHER                                      |       |  |
| Comment:           | NFPA placards on separator and meterhouse. |       |  |
| Corrective Action: |  | Date: |  |
| Type               | OTHER                                      |       |  |
| Comment:           | Warning signs on pumpjack enclosure.       |       |  |
| Corrective Action: |  | Date: |  |

**Emergency Contact Number:**

|                    |   |       |  |
|--------------------|---|-------|--|
| Comment:           | 24 hour operator contact number and 911 local emergency number posted on well location signage. |       |  |
| Corrective Action: |   | Date: |  |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 270212 Type: WELL API Number: 067-08897 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 06/30/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment                       |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|-------------------------------|
| Rip Rap          | Pass            | Gravel                  | Pass                  |  |                          |                               |
| Waddles          | Pass            | Ditches                 | Pass                  | Material Handling And Spill Prevention | Pass                     | Container within containment. |
| Berms            | Pass            |                         |                       |  |                          |                               |
| Gravel           | Pass            |                         |                       |  |                          |                               |
| Ditches          | Pass            | Culverts                | Pass                  |  |                          |                               |
| Compaction       | Pass            |                         |                       |  |                          |                               |

Comment: [Corrective action identified in FIR Doc.#712700749 has been completed. See photos #1-#6.](#)  
[No visible erosion or sediment migration observed during inspection.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 712700894    | INSPECTION PHOTOS | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6326953">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6326953</a> |