

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/16/2023

Submitted Date:

11/17/2023

Document Number:

712700887

FIELD INSPECTION FORM

Loc ID 306870 Inspector Name: Pattillo, Curtis On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Findings:

- 11 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|-------|-------------------------------|------------------------------------|
| , General | | sjninspections@ikavenergy.com | All SW Inspections |
| Labowskie, Steve | | steve.labowskie@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 271341 | WELL | PR | 03/01/2016 | CBM | 067-08923 | BEAVER CREEK 2 | PR |

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a follow up field inspection to verify completion of corrective actions identified in FIR Document #712700754 submitted 10/17/2023. Corrective actions identified have been completed.

Two solar arrays have been installed on the location. See attached inspection photos.

Equipment inventory is listed on previous inspection, no change to location production equipment.

| Location | | | |
|--|---|--------|-----------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Access from CR 526. Locked gate, 2C40 key. | | |
| Corrective ActionL | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | OTHER | | |
| Comment: | Warning signs on pumpjack fencing. | | |
| Corrective Action: | | | Date: |
| Type | OTHER | | |
| Comment: | NFWA placards on separator and meterhouse. | | |
| Corrective Action: | | | Date: |
| Type | WELLHEAD | | |
| Comment: | Metal sign posted at location entrance. | | |
| Corrective Action: | | | Date: |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Content and volume label, NFWA placard on produced water tank. | | |
| Corrective Action: | | | Date: |
| Emergency Contact Number: | | | |
| Comment: | 24 hour operator contact number and 911 local emergency number posted on well location signage. | | |
| Corrective Action: | | | Date: |
| Good Housekeeping: | | | |
| Type | WEEDS | | |
| Comment: | Corrective action identified in FRI Doc.#712700754 has been completed. Weeds throughout location have been removed. Solar arrays have been installed on the north side and east side of the location. See photos #1-#4. | | |
| Corrective Action: | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | <input style="width: 100%;" type="text"/> | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Equipment: | | | |
| Type: Ancillary equipment | # 1 | | corrective date |
| Comment: | Two separate solar arrays have been installed. One array is located on the north side of the fenced location. The second is located on the east side of the location. | | |
| Corrective Action: | | | Date: |
| Venting: | | | |

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 271341 Type: WELL API Number: 067-08923 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 06/28/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Ditches | Pass | Ditches | Pass | | | |
| Gravel | Pass | Gravel | Pass | | | |
| Compaction | Pass | Culverts | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403599830 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6326966 |
| 712700891 | INSPECTION PHOTOS | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6326950 |