

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/16/2023

Submitted Date:

11/17/2023

Document Number:

712700888

**FIELD INSPECTION FORM**

Loc ID 325962 Inspector Name: Pattillo, Curtis On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10749  
Name of Operator: SIMCOE LLC  
Address: 1199 MAIN AVE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215640	WELL	PR	04/01/1989	CBM	067-07245	ALBRIGHT-TRIMBLE 1	PR

**General Comment:**

SW Compliance Specialist Curtis Pattillo conducted a follow up field inspection to verify completion of corrective actions identified in FIR Document #712700752 submitted 1/17/2023. Corrective actions have been completed.  
Equipment inventory is listed on previous inspection, no change to location equipment.

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Access from CR527. Electric code gate, private road. Gravel surface.		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Metal sign posted on production equipment fencing near location entrance.		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Label on chemical additive container.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Warning signs on pumpjack enclosure.		
Corrective Action:			Date:
Type	OTHER		
Comment:	NFPA placard on separator and meterhouse.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	24 hour operator contact number and 911 local emergency number posted on well location signage.		
Corrective Action:			Date:
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Corrective action identified in FIR Doc.#712700752 has been completed. See photos #1 -#4.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			
Type			
Comment:			

Corrective Action:

Date:



**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Culverts	Pass	Material Handling And Spill Prevention	Pass	Container within containment.
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Ditches	Pass			

Comment: No visible erosion or sediment migration observed during inspection.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403599852	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6326984">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6326984</a>
712700893	INSPECTION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6326952">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6326952</a>