

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/14/2023

Submitted Date:

11/17/2023

Document Number:

701007628

FIELD INSPECTION FORMLoc ID 321871 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 34105

Name of Operator: GILBERT-STEWART OPERATING LLC

Address: 1801 BROADWAY STE 200

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gilbert, Kent	303-534-1686	kgoil@msn.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208289	WELL	TA	01/01/2020	OW	017-07224	AKERS 2	PA

General Comment:

P&A Inspection

Location

Lease Road:			
Type	Access		
comment:	Trail through farm ground		
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by cathodic rectifier		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Pump Jack	# 0		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Electric panel and cathodic rectifier		
Corrective Action:	Remove equipment from location to begin final reclamation process	Date:	12/14/2023

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 208289 Type: WELL API Number: 017-07224 Status: TA Insp. Status: PA**Cement**Cement ContractorContractor Name: HP Oilfield Service

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging OperationsDepth Plugs(feet range): 3674/2345/1600/500Cement Volume (sx): 300 SXS

Good Return During Job: _____

Cement Type: Class AComment:

PEAK WIRELINE, HP OILFIELD SERVICES, EASTERN COLORADO WELL SERVICE. MIRU PEAK, RIH W/CICR SET @ 3674'. MIRU ECWS, RIH W/TBG, STING INTO CICR. MIRU HP, PUMP 45 SXS THRU CICR W/5 SXS ON TOP. MIRU ECWS, POOH W/TBG. MIRU PEAK, RIH W/GUN, PERF @ 2395'. RIH W/CICR, WIRELINE SET @ 2345'. MIRU ECWS, RIH W/TBG STING INTO CICR. MIRU HP, PUMP 45 SXS THRU W/5 SXS ON TOP. MIRU ECWS, POOH W/TBG. MIRU PEAK, RIH W/GUN, PERF @ 1650' AND 500'. RIH W/CICR TO 1600'. MIRU ECWS, RIH W/TBG, STING INTO CICR. MIRU HP, PUMP 45 SXS THRU W/5 SXS ON TOP. MIRU ECWS, POOH W/TBG TO 1000'. MIRU HP, PUMP 30BBLS WATER TO FLUSH CSG. MIRU ECWS, POOH W/TBG. MIRU HP, PUMP 100 SXS CMT (LEAD) 50 SXS (TAIL) W/CaCl. SHUT IN WELL.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: [Location and access are farmed over](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701007638	Location photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6327110