


Storm Water Management and Erosion control

Location Name: MUSTANG RESOURCES LLC JUHAN RULISON UNIT 34-94-6S-94W Pad

Location ID: 322325



Location Overview: Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area & Bald Eagle Roost site. Location is approximately 500 yards from Spruce Creek.

Section/Township/Range: 34 6S94W



Storm water Management and Erosion control

Location Name: MUSTANG RESOURCES LLC JUHAN RULISON UNIT 34-94-6S-94W Pad

Location ID: 322325



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control

Location Name: MUSTANG RESOURCES LLC JUHAN RULISON UNIT 34-94-6S-94W Pad

Location ID: 322325



Photo # 6928 Lack of stabilization/compaction/insufficient BMP's

Photo # 6929 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control

Location Name: MUSTANG RESOURCES LLC JUHAN RULISON UNIT 34-94-6S-94W Pad

Location ID: 322325



Photo # 6930 Lack of stabilization/compaction/insufficient BMP's



Photo # 6931 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control

Location Name: MUSTANG RESOURCES LLC JUHAN RULISON UNIT 34-94-6S-94W Pad

Location ID: 322325



Photo # 6932 Lack of stabilization/compaction/insufficient BMP's



Photo # 6933 Lack of stabilization/compaction/insufficient BMP's