

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/16/2023

Submitted Date:

11/17/2023

Document Number:

708902263

**FIELD INSPECTION FORM**Loc ID 322325 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10550

Name of Operator: MUSTANG RESOURCES LLC

Address: PO BOX 13550

City: BAKERSFIELD State: CA Zip: 93389

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                    | Comment |
|--------------|-------|--------------------------|---------|
| , Mustang    |       | nwelch@vaqueroenergy.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name                   | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------------------|-------------|
| 210278      | WELL | SI     | 07/01/2023  | GW         | 045-06034 | JUHAN RULISON UNIT 34-94-6S-94W | SI          |

**General Comment:****CECMC Inspection Report Summary**

On 11/16/2023 at approximately 12:24 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection at MUSTANG RESOURCES LLC JUHAN RULISON UNIT 34-94-6S-94W Pad.

Location # 322325 in Garfield County Colorado.

Location is within High Priority/Density/Black Bear Habitat areas &amp; in close proximity to NSO Habitat area &amp; Bald Eagle Roost site.

Location is approximately 500 yards from Spruce Creek.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Stormwater - Lack of stabilization/compaction on location with a CA date of 12/02/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

**Location**

|                    |        |       |  |
|--------------------|--------|-------|--|
| <b>Lease Road:</b> |        |       |  |
| Type               | Access |       |  |
| comment:           |        |       |  |
| Corrective Action  |        | Date: |  |

Overall Good: ☐

|                      |                 |       |  |
|----------------------|-----------------|-------|--|
| <b>Signs/Marker:</b> |                 |       |  |
| Type                 | WELLHEAD        |       |  |
| Comment:             |                 |       |  |
| Corrective Action:   |                 | Date: |  |
| Type                 | BATTERY         |       |  |
| Comment:             | No tank battery |       |  |
| Corrective Action:   |                 | Date: |  |

Emergency Contact Number:

Comment: 911/1-888-291-8588

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                          |   |       |                 |
|--------------------------|---|-------|-----------------|
| <b>Equipment:</b>        |   |       | corrective date |
| Type: Plunger Lift       | # 0   |       |                 |
| Comment:                 | Well is not on plunger lift   |       |                 |
| Corrective Action:       |   | Date: |                 |
| Type: Deadman # & Marked | # 4   |       |                 |
| Comment:                 | Marked  |       |                 |
| Corrective Action:       |   | Date: |                 |
| Type: Bradenhead         | # 1   |       |                 |
| Comment:                 | No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible. |       |                 |
| Corrective Action:       |   | Date: |                 |
| Type: Gas Meter Run      | # 1   |       |                 |
| Comment:                 |   |       |                 |
| Corrective Action:       |   | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

|  |  |  |  |
|--|--|--|--|
|  |  |  |  |
|--|--|--|--|

| Inspected Facilities |                                     |       |      |             |           |         |    |               |    |
|----------------------|-------------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 210278                              | Type: | WELL | API Number: | 045-06034 | Status: | SI | Insp. Status: | SI |
| Producing Well       |                                     |       |      |             |           |         |    |               |    |
| Comment:             | Producing, well not on plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:   |                                     |       |      | Date:       |           |         |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment                          |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|----------------------------------|
|                  |                 | Compaction              |                       |               |                          |                                  |
|                  |                 | Gravel                  |                       |               |                          | Sparse                           |
| Compaction       | Fail            |                         |                       |               |                          | Lack of stabilization/compaction |
| Gravel           | Fail            |                         |                       |               |                          | Sparse to none                   |

Comment: 1. Lack of stabilization/compaction/insufficient BMP's on location  
  
Please refer to Reclamation inspection document # 702801442 conducted on 04/05/2023. Reclamation inspection also noted & documented lack of stabilization & insufficient BMP's on location.

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.

Date: 12/02/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

| Comment   | User     | Date       |
|---|----------|------------|
| Please refer to Stormwater for observed compliance issue. | smelserw | 11/17/2023 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                               | URL   |
|--------------|---|---|
| 708902264    | Inspection 708902263 Stormwater photo log | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6327740">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6327740</a> |
| 708902265    | Inspection 708902263 photo log            | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6327741">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6327741</a> |