

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/13NWNW

Location ID: 312601

Date: 11/15/2023



Location Entrance – Photo #07534



Wellhead/Weeds/Inaccurate Sign – Photo #07548

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/13NWNW

Location ID: 312601

Date: 11/15/2023



Separator/Gas Meter/Wildlife Entry Hazard/Weeds – Photo #07549



Tank Battery/Weeds – Photo #07553

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/13NWNW

Location ID: 312601

Date: 11/15/2023



Storage of Unused Equipment – Photo #07543



Storage of Unused Equipment/Weeds – Photo #07541

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/13NWNW

Location ID: 312601

Date: 11/15/2023



Storage of Unused Equipment/Wildlife Entry Hazard – Photo #07540



Storage of Unused Equipment/Weeds – Photo #07545

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/13NWNW

Location ID: 312601

Date: 11/15/2023



Storage of Unused Equipment/Weeds – Photo #07542



Debris/Weeds – Photo #07547

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/13NWNW

Location ID: 312601

Date: 11/15/2023



Location Lacks Stabilization – Photo #07557



**Insufficient Vehicle Tracking BMPs at Location
Entrance/Exit – Photo #07558**

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/13NWNW

Location ID: 312601

Date: 11/15/2023



Waddle BMP Degradation— Photo #07554



Lease Road Ditch Full of Sediment Running Onto Road – Photo #07556