

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2023

Submitted Date:

11/18/2023

Document Number:

708301233

FIELD INSPECTION FORM

Loc ID 312601	Inspector Name: Morris, Matthew	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 17 Number of Comments 10 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: 10770 Name of Operator: VISION ENERGY LLC Address: P O BOX 370 City: IGNACIO State: CO Zip: 81137				
ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE				

Contact Information:			
Contact Name	Phone	Email	Comment
ENERGY, VISION		mco@visionenergy.biz	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221999	WELL	SI	05/01/2010	CBM	077-08601	SOUTH SHALE RIDGE 4-13	SI

General Comment:

[COGCC Inspection Report Summary](#)

On 11/15/2023 at approximately 10:45, Compliance Inspector Matthew Morris conducted a follow-up inspection at VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/13NWNW at Location ID #312601 in Mesa County, Colorado.

Corrective actions from FIR #708300856 have not been completed and remain in effect.

During the inspection, the following compliance issues were observed:

- 1) Debris present across entire production area
- 2) Storage of supplies and equipment/unused equipment on location
- 3) Weeds present across entire production area
- 4) Signs; inaccurate signs at tank battery and wellhead/tank label missing tank capacity
- 5) Wildlife entry hazard on unused tank and vertical separator
- 6) Earth berm permeability inadequate due to weed growth
- 7) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, and/or Wildlife Management area.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign not posted at wellhead.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	05/18/2023
Type	BATTERY		
Comment:	Inaccurate operator information on battery sign.		
Corrective Action:	Install sign with current operator information to comply with Rule 605.e.	Date:	05/18/2023
Type	TANK LABELS/PLACARDS		
Comment:	Tank label missing volume capacity.		
Corrective Action:	Install label with tank capacity information to comply with Rule 605.h.	Date:	05/18/2023

Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds and undesirable plant species present across entire location.		
Corrective Action:	Remove weeds and undesirable plant species from location to comply with Rule 606.	Date:	04/25/2023
Type	STORAGE OF SUPL		
Comment:	Storage of supplies and equipment on location.		
Corrective Action:	Remove stored supplies and equipment from location to comply with Rule 606.	Date:	04/25/2023
Type	DEBRIS		
Comment:	Debris present across entire location.		
Corrective Action:	Remove debris from location to comply with Rule 606.	Date:	04/25/2023
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment on location includes pump jacks, separator, fiberglass tanks, and other miscellaneous equipment.		
Corrective Action:	Remove unused equipment from location to comply with Rule 606.	Date:	05/18/2023
Type	OTHER		
Comment:	Vertical separator and unused fiberglass storage tank are damaged and pose a wildlife entry hazard.		
Corrective Action:	Install wildlife protection equipment on separator and tank to comply with Rule 608.a.	Date:	04/23/2023

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Bird Protectors	# 2		

Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	FIBERGLASS AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	Capacity not posted	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Berm permeability is inadequate due to weed growth in berm.			
Corrective Action:	Repair earth berm to comply with Rule 603.o.			
				Date: 05/18/2023

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 221999 Type: WELL API Number: 077-08601 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				BMP insufficient
Other	Fail					Insufficient vehicle tracking BMPs
Waddles	Fail					BMP degraded and insufficient
		Compaction				
		Gravel				
Gravel						
Compaction	Fail					Location lacks stabilization

Comment:
 1) No BMP in place to prevent sediment run-on to location
 2) Inadequate BMPs in place to minimize sediment transport from location
 3) Inadequate vehicle tracking BMPs in place to minimize sediment transportation
 4) Rill erosion cutting through lease road
 5) Lease road ditch full of sediment and flows onto lease road

Corrective Action: **Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to comply with Rule 1002.**

Date: 05/03/2023

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708301234	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6328086