

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/09/2023

Submitted Date:

11/20/2023

Document Number:

710500111

**FIELD INSPECTION FORM**Loc ID 308346 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

10 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beardslee, Tom		tom.beardslee@state.co.us	
, ENR	719-846-7898	cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257988	PIT	AC			-	Bald Eagle TR 44-18 OFFSITE	EI
268153	WELL	PR	01/26/2004	GW	071-07867	BALD EAGLE 44-18TR	EI
270431	PIT	AC			-	BALD EAGLE 44-18 TR ONSITE	EI
308346	LOCATION	AC			-	BALD EAGLE-634S65W 18SESE	EI

**General Comment:**

This is an Environmental Inspection for the Bald Eagle 44-18 TR, Facility 308346 Active well location located in Las Animas County Co. A Form 15 Doc# 403547722 was filed to update pit coordinates Facility ID 270431 AKA Bald Eagle 44-18 TR Onsite Pit

**Location****Lease Road:**

Type	Access		
comment:	There are areas along the Access Road with Riling and Erosion due to Stormwater runoff.		
Corrective Action:	Maintain Access road Per Rule 1002.f.	Date:	12/15/2023

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Well Placard Coordinates do not match ECMC records		
Corrective Action:	Maintain Signage per Rule 605.d	Date:	01/10/2024

**Emergency Contact Number:**

Comment:			
Corrective Action:			Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: <u>257988</u>	Type: <u>PIT</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>
Facility ID: <u>268153</u>	Type: <u>WELL</u>	API Number: <u>071-07867</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>270431</u>	Type: <u>PIT</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>
Facility ID: <u>308346</u>	Type: <u>LOCATION</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 270431Lat: 37.081053Long: -104.705895

Reference Point: \_\_\_\_\_

Other: \_\_\_\_\_

Length: \_\_\_\_\_

Width: \_\_\_\_\_

**Lining:**

Liner Type:

Liner Condition:

Comment:

The Onsite pit for the Bald Eagle 44-18 TR does not meet freeboard requirements. The location for the onsite pit is a shallow depression in the ground, which would not hold water.

Corrective Action

File a Form 15 to modify pit to meet freeboard requirements or close facility with a Form 27

Date: 01/11/2024**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

**Netting:**

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date:

Type: Produced WaterLined: NOPit ID: 257988Lat: 37.081119Long: -104.705605

Reference Point: \_\_\_\_\_

Other: \_\_\_\_\_

Length: \_\_\_\_\_

Width: \_\_\_\_\_

**Lining:**

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date:

**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

**Netting:**

Netting Type:

Netting Condition: \_\_\_\_\_

Comment:				Date:
Corrective Action				
Anchor Trench Present:	Oil Accumulation:	2+ feet Freeboard:		Date:
Comment:				
Corrective Action				
Permit:	Facility ID	Permit Num	Expiration Date	
	270431	11255961		
Monitoring:	Monitoring Type	Comment		
	Chain	In Place		
	Telemetry	Not Working at the time of inspection		

**COGCC Comments**

Comment	User	Date
<a href="#">Telemetry Equipment not working at the time if inspection</a>	sanchezcc	11/09/2023
<a href="#">Well Placard Coordinates do not match ECMC records Maintain Signage per Rule 605.d.</a>	sanchezcc	11/09/2023
<a href="#">The Onsite pit for the Bald Eagle 44-18 TR does not meet freeboard requirements. The location for the onsite pit is a shallow depression in the ground, which would not hold water File a Form 15 to modify pit to meet freeboard requirements or close facility with a Form 27</a>	sanchezcc	11/09/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500112	Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6328491">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6328491</a>