

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate	
Corrective Action:		Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Debris/Dead Vegetation inside fenced area		
Corrective Action:	Comply with Rule 606	Date:	11/27/2023

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Chainlink		
Corrective Action:		Date:	

Equipment:

Type:	Ancillary equipment	# 1		corrective date
Comment:	Automation RTU			
Corrective Action:		Date:		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 200840 Type: WELL API Number: 001-06243 Status: AC Insp. Status: AC

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On (11/15/2023) at approximately (10:20am). I, Inspector Keith Huck, conducted an on-site inspection. Operator: Colorado Interstate Gas Location name: Totem#09 API # 001-06243 Location ID #: 319677 County: Adams While there, I observed a (AC) well. During this inspection the following possible compliance issues were observed: Debris inside fenced area Comply with Rule 606 CA Date: 11/27/2023 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	huckk	11/20/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709700219	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6328953