

Inspection Photos

11/14/2023

Operator: CAERUS PICEANCE LLC #10456

Location ID: 478266

Inspection Doc: 696205422

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 478266



Photo 2: Water truck in use to mitigate fugitive dust.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 478266



November 14, 2023



39.6846045N 108.1406941W
November 14, 2023

Photo 3: Wildlife protection BMPs missing at spill prevention/containment measures. Wildlife mortality (mouse, arrow) observed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 478266



Photo 4: Photos taken from the access road entrance on the north end of the Location. Photos examples showing drain pipes per the Form 2A Location drawing/SWMP have not been installed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 478266



Photo 5: Photo taken from the south end of the Location; Photo example showing BMPs to minimize erosion at the fill slopes remain missing or insufficient; velocity checks not observed within ditch.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 478266



Photo 6: Photo shows improperly covered materials on Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Operat

56

39.68359382N 108.14156243W
November 14, 2023

39.68363126N 108.14155883W
November 14, 2023

39.68358423N 108.14154121W
November 14, 2023

Photo 7: Photos examples showing new material spills on the southwest end of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 478266



Photo 8: Photos 8-10 taken from the topsoil stockpiles along the perimeter of the Location. Photos examples showing areas of the stockpiles where hydromulch is not longer in proper functioning condition.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 478266



Photo 9: See comments under photo 8.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 478266



Photo 10: See comments under photo 8.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 478266



Photo 11: Photo taken from the northwest end of the Location. Photo shows sediment trap #2 appears unchanged in size. Photo also example showing areas of the topsoil stockpiles where hydromulch is no longer in proper functioning condition.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources