

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/08/2023

Submitted Date:

11/20/2023

Document Number:

713600409

FIELD INSPECTION FORM

 Loc ID 322277 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 17210
 Name of Operator: CINNAMON CREEK OIL & GAS INC
 Address: P O BOX 544
 City: WALSH State: CO Zip: 81090
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 9 Number of Comments
5 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Beardslee, Tom		tom.beardslee@state.co.us	
MILLS RICK		rickmills000@gmail.com	
Mills, Hellen		helening1221@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210100	WELL	PR	09/01/2020	OW	043-40037	YANKOVICK 1	RI

General Comment:

This is a follow up location inspection conducted by area reclamation specialist.
 Previous inspection corrective actions have not been completed.
 See attached photos and additional details within this report.

Location			
Lease Road:			
Type	Access		
comment:	Operator must ensure vehicles aren't tracking mud onto landowners graveled area.		
Corrective ActionL		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	It looks like the tank capacity has been posted on front of tank 100BBL.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			Date: _____
Corrective Action:			
Good Housekeeping:			
Type	WEEDS		
Comment:	The weeds and dry vegetation were cut however the debris remains and needs to be removed. This area needs to be kept clear of vegetation/debris for safety.		
Corrective Action:	REMOVE WEEDS and DEBRIS PER RULE 606		Date: <u>11/19/2023</u>
Type	OTHER		
Comment:	AREA OF IMPACTED SOIL UNDER PUMPJACK GEAR BOX STILL REMAINS. It appears soils were shoveled over the stoned material to try and cover up. Stained soils must be cleaned up and properly disposed. Previous corrective action was not completed and must be done immediately.		
Corrective Action:	: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D		Date: <u>11/19/2023</u>
Type	OTHER		
Comment:	THERE ARE EXPOSED WIRE CONNECTIONS INSIDE WOOD ELECTRIC PANEL BOX.		
Corrective Action:	Securely fasten all valves, pipes, fittings, electric equipment and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 603.O(6). Previous corrective action was not completed and must be done immediately.		Date: <u>11/19/2023</u>
Type	TRASH		
Comment:	Trash was removed.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Bradenhead	#		corrective date
Comment:	BRADENHEAD IS NOT ACCESSABLE.		

Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).	Date:	11/19/2023
--------------------	------------------------------------------------------------------------------------------------	-------	------------

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs			38.426278,-105.209894

Comment: THERE APPEARS TO BE A RUBBER FLAP COVER ON TANK BATTERY WITH NO SAFETY VALVE INSTALLED ON TANK.

Corrective Action:	Tanks will function as sealed and ventless with gas released only through a vapor control system or properly sized pressure relief valve. per Rule 608.a.(9).	Date:	10/21/2023
--------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------	-------	------------

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713600411	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6329706