

Storm Water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MACKELY 34-12-6S-94W
Location ID: 322467



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas/Bald Eagle Roost
Site & in close proximity to NSO Habitat area. Location is
approximately 234 yards from Spruce Creek & approximately
415 yards from the Colorado River.
Section/Township/Range: 34 6S94W**

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MACKELY 34-12-6S-94W
Location ID: 322467



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MACKELY 34-12-6S-94W
Location ID: 322467



Photo # 6901 Lack of stabilization/compaction



Photo # 6902 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MACKELY 34-12-6S-94W
Location ID: 322467



Photo # 6903 Lack of stabilization/compaction



**Photo # 6904 Erosion & transport of sediment off location
(NE area of location)**

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MACKELY 34-12-6S-94W
Location ID: 322467



**Photo # 6905 Erosion & transport of sediment off location
(NE area of location)**



**Photo # 6906 Erosion & transport of sediment off location
(NE area of location)**