

Inspection Photos

Location Name: MUSTANG RESOURCES LLC LOUTHAN 34-32-6S-94W Pad

Location ID: 323819



Photo # 7086 From entrance to location



Photo # 7087 Location

Inspection Photos

Location Name: MUSTANG RESOURCES LLC LOUTHAN 34-32-6S-94W Pad

Location ID: 323819



Photo # 7088 Location



Photo # 7089 Location

Inspection Photos

Location Name: MUSTANG RESOURCES LLC LOUTHAN 34-32-6S-94W Pad

Location ID: 323819



Photo # 7090 Debris



Photo # 7091 Debris

Inspection Photos

Location Name: MUSTANG RESOURCES LLC LOUTHAN 34-32-6S-94W Pad

Location ID: 323819



Photo # 7092 Debris/Small manure pile & manure spread over location in background



Photo # 7093 Debris/Small manure pile & manure spread over location in background

Inspection Photos

Location Name: MUSTANG RESOURCES LLC LOUTHAN 34-32-6S-94W Pad

Location ID: 323819



Photo # 7094 Debris/Small manure pile



Photo # 7095 Debris/Small manure pile