



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type PUMP JACK

Comment: [fabricated fencing](#)

Corrective Action:

Date: \_\_\_\_\_

**Equipment:**

corrective date

Type: Bradenhead # 1

Comment: [plumbed to surface](#)

Corrective Action:

Date: \_\_\_\_\_

Type: Prime Mover # 1

Comment: [electric motor](#)

Corrective Action:

Date: \_\_\_\_\_

Type: Pump Jack # 1

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Ancillary equipment # 1

Comment: [electric](#)

Corrective Action:

Date: \_\_\_\_\_

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Flaring:**

Type

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Inspected Facilities**

Facility ID: 204454 Type: WELL API Number: 005-06539 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 11/20/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: due this month

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<u>At time of inspection location appears to be in compliance with ECMC rules. At time of inspection weather conditions were warm, calm, overcast.</u>	<u>medinaj</u>	<u>11/16/2023</u>

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
<u>699505150</u>	<u>inspection pictures</u>	<u>http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6330274</u>