

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2023

Submitted Date:

11/21/2023

Document Number:

710500123

FIELD INSPECTION FORMLoc ID 422206 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10417

Name of Operator: INCREMENTAL OIL & GAS (FLORENCE) LLC

Address: 113 N SANTA FE AVE

City: FLORENCE State: CO Zip: 81226

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hart, Tim	309-999-5420	thart@fremontpetroleum.com	All Inspections
Harkins, Liz	719-429-4513	Lharkins@austineexploration.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422196	WELL	PR	01/01/2022	OW	043-06203	Triggerfish 22-31	EI
422206	LOCATION	AC			-	Trumpetfish 22-31	EI
426625	WELL	SI	09/01/2023	OW	043-06214	TRUMPETFISH 22-31R	EI

General Comment:

This is an Environmental Inspection for the Trumpetfish 22-31R and Triggerfish 22-31, Location Id 422206, Active well location Located in Fremont County Co

LocationOverall Good: ☒

Emergency Contact Number:

Comment: ECMC Records show the Trumpetfish 22-31R to be in the SW/NE quarter of Section 31; T19S; R69W, after a review of the GIS map the location sits in the SE/NW Quarter as the Well Placard indicates.

Corrective Action: Operator shall work with ECMC OGLA Group to update Scout Card Records,

Date: 12/21/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
Produced Water	Tank	<= 1 bbl		
Comment: There is a area of stained soil located at the Tank Battery between the Produced Water Tank and Oil Tank.				
Corrective Action: Clean Up stained soil and maintain equipment per Rule 608.e.			Date:	12/21/2023

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Pump Jack	#		corrective date
Comment: There is soil staining at the wellhead and at the back of the Trumpetfish Pumping Unit			
Corrective Action: Cleanup stained soil and maintain equipment per Rule 608.e.		Date:	12/21/2023

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: <u>422196</u>	Type: <u>WELL</u>	API Number: <u>043-06203</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>422206</u>	Type: <u>LOCATION</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>
Facility ID: <u>426625</u>	Type: <u>WELL</u>	API Number: <u>043-06214</u>	Status: <u>SI</u>	Insp. Status: <u>EI</u>

COGCC Comments

Comment	User	Date
ECMC Records show the Trumpetfish 22-31R to be in the SW/NE quarter of Section 31; T19S; R69W, after a review of the GIS map the location sits in the SE/NW Quarter as the Well Placard indicates. Operator shall work with ECMC OGLA group to update Scout Card Records,	sanchezcc	11/20/2023
There is an area of stained soil located at the Tank Battery between the Produced Water Tank and Oil Tank. Clean Up stained soil and maintain equipment per Rule 608.e.	sanchezcc	11/20/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500124	Location Map	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6330532
710500125	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6330533