

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2023

Submitted Date:

11/21/2023

Document Number:

710500126

FIELD INSPECTION FORMLoc ID 425246 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10417

Name of Operator: INCREMENTAL OIL & GAS (FLORENCE) LLC

Address: 113 N SANTA FE AVE

City: FLORENCE State: CO Zip: 81226

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hart, Tim	309-999-5420	thart@fremontpetroleum.com	All Inspections
Harkins, Liz	719-429-4513	Lharkins@austineexploration.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
425246	LOCATION	AC			-	Swordfish 13-31	EI
425247	WELL	SI	01/01/2023	OW	043-06212	Swordfish 13-31	EI

General Comment:

This is an Environmental Inspection for the Swordfish 13-31, Location ID 425246, Shut-in Well Location in Fremont County Co

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Well Placard missing well Numbers

Corrective Action: Add well numbers to well placard, comply with Rule 605.d.

Date: 01/14/2024

Good Housekeeping:

Type	WEEDS		
Comment:	There are weeds located inside the secondary containment berms for the Tank Battery and throughout the Location		
Corrective Action:	Remove Undesirable Plant Species from tank berms and location. Comply with Rule 606		Date: 07/31/2023
	There was a Interim Reclamation Inspection conducted on the location on 07/13/2023, Corrective Actions Due date will reflect Inspection Doc# 690204439 CA due dates		

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Pump Jack	#		
Comment:	There is soil staining at the wellhead		
Corrective Action:	Clean up stained soils and maintain equipment Per Rule 608.e		Date: 12/21/2023

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: <u>425246</u>	Type: <u>LOCATION</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>
----------------------------	-----------------------	----------------------	-------------------	-------------------------

Facility ID: <u>425247</u>	Type: <u>WELL</u>	API Number: <u>043-06212</u>	Status: <u>SI</u>	Insp. Status: <u>EI</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

COGCC Comments

Comment	User	Date
Remove Undesirable Plant Species from tank berms and location. Comply with Rule 606	sanchezcc	11/20/2023
There was a Interim Reclamation Inspection conducted on the location on 07/13/2023, Corrective Actions Due date will reflect Inspection Doc# 690204439 CA due		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500131	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6330535