

Inspection Photos
Location Name: McCarty #2
API #123-10514



Energy & Carbon Management Commission
40.29469, -104.8913, 1488.7m, 56°
11/21/2023 09:53:55


Production facility



Energy & Carbon Management Commission
40.29457, -104.8907, 1484.0m, 6°
11/21/2023 10:14:00

Battery sign

Inspection Photos
Location Name: McCarty #2
API #123-10514



Wellhead sign



Unused equipment


Inspection Photos

Location Name: McCarty #2
API #123-10514



Energy & Carbon Management Commission
40.29457, -104.8907, 1484.0m, 46°
11/21/2023 10:14:05

Weeds



Energy & Carbon Management Commission
40.29454, -104.89098, 1477.2m, 328°
11/21/2023 10:23:36

DCP meter calibration card