

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/21/2023

Submitted Date:

11/21/2023

Document Number:

702402525

FIELD INSPECTION FORMLoc ID 434300 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10633

Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------------|---------------------------------|
| , | | Inspections@civiresources.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------------------|-------------|
| 434272 | WELL | PR | 02/08/2015 | OW | 123-38068 | Edith Ann-Duckworth 4E-21H O268 | PR |
| 434275 | WELL | PR | 10/01/2018 | OW | 123-38070 | Edith Ann-Duckworth 4F-21H P268 | PR |
| 434276 | WELL | PR | 08/01/2023 | OW | 123-38071 | Edith Ann-Duckworth 4C-21H O268 | PR |
| 434278 | WELL | PR | 08/01/2023 | OW | 123-38073 | Edith Ann-Duckworth 4A-21H O268 | PR |
| 434279 | WELL | PR | 02/08/2015 | OW | 123-38074 | Edith Ann-Duckworth 4G-21H O268 | PR |
| 434286 | WELL | PR | 04/01/2021 | OW | 123-38081 | Edith Ann-Duckworth 4D-21H O268 | PR |
| 434305 | WELL | PR | 03/01/2021 | OW | 123-38085 | Edith Ann-Duckworth 4H-21H O268 | PR |
| 434816 | WELL | PR | 08/01/2023 | OW | 123-38348 | Edith Ann-Duckworth 4B-21H O268 | PR |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|--------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | adequate x 8 | | |
| Corrective Action: | | Date: | |

| | |
|---------------------------|-------------|
| Emergency Contact Number: | |
| Comment: | |
| Corrective Action: | Date: _____ |

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

| | | | |
|--------------------|-----------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | chainlink | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|---------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Bradenhead | # 8 | | |
| Comment: | appear plumbed to surface | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 8 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 10 | | |
| Comment: | automation | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|----|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 434272 Type: WELL API Number: 123-38068 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 02/03/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 434275 Type: WELL API Number: 123-38070 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 02/03/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 12 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 434276 Type: WELL API Number: 123-38071 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 02/03/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 434278 Type: WELL API Number: 123-38073 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/03/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 434279 Type: WELL API Number: 123-38074 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/03/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 434286 Type: WELL API Number: 123-38081 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/03/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 13 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 434305 Type: WELL API Number: 123-38085 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/03/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 48 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

| | | | | | | | | | |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 434816 | Type: | WELL | API Number: | 123-38348 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/03/2023

Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|--|--------|------------|
| <p>ECMC Inspection Report Summary</p> <p>On Tuesday 11-21-2023 at approximately 1420 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection:</p> <p>Operator: Civitas/Crestone Peak</p> <p>Location name: Edith Ann-Duckworth 21H-O268</p> <p>Location ID # 434300</p> <p>Well Name:</p> <p>API # 05-</p> <p>County: Weld</p> <p>Weather: Clear, Sunny.</p> <p>Location: Dry.</p> <p>While there, I observed a Multi well pad, PR at the time of the inspection.</p> <p>During this inspection, I observed no compliance issues:</p> <p>See attached photos.</p> <p>No follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.</p> | revasr | 11/21/2023 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------|---|
| 702402526 | location pics | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6331138 |