

Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	Open Top		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Shares berm with crude tank.				
Corrective Action:					Date:

Venting:

Yes/No	YES		
Comment:	Rule 903.d.(2). Venting or Flaring Natural Gas.		
Corrective Action:	Gas being vented or flared during non-upset condition without prior approval from COGCC. Immediately cease venting/flaring. Submit Form 4 for review and approval to vent or flare. Corrective Action Date 24 hours. See attached video # 1		Date: 11/16/2023

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 201895 Type: WELL API Number: 001-07299 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 05/02/2023 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Appeared to be plumbed to surface.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday November 15th, 2023 at approximately 10:48am. I, Inspector Chane Finkenbinder, conducted an on-site inspection. Operator: KP KAUFMANN Location name: Green #1 API #001-07299 Location ID #: 319921 County: Adams While there, I observed a Producing well. During this inspection the following possible compliance issues were observed: Rule 903.d.(2). Venting or Flaring Natural Gas. Gas being vented or flared during non-upset condition without prior approval from COGCC. Immediately cease venting/flaring. Submit Form 4 for review and approval to vent or flare. Corrective Action Date 24 hours. See attached video# 1 Contacted Mani Silva with KP KAUFMANN about the instance. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	finkenbc	11/15/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403597323	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6324798
700901753	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6324734
700901754	OPGAL video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6324735