

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2023

Submitted Date:

11/16/2023

Document Number:

712700879

**FIELD INSPECTION FORM**Loc ID 306880 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

25 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272399	WELL	PR	10/01/2021	CBM	067-08949	MORRISON FEDERAL 2	PR

**General Comment:**

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Access from CR 525. Private road through residences. Gravel surface.		
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Content and volume label, NFPA placard on produced water tank.		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Label on container.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Metal sign posted on pumpjack fencing.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Warning signs on pumpjack.		
Corrective Action:			Date:
Type	OTHER		
Comment:	NFPA placads on separator and meterhouse. Buried pipeline carsonite markers.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	24 hour operator contact number and 911 local emergency number posted on well location signage.		
Corrective Action:			Date:
<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	Observed irrigation pipe and fuel storage tanks stored on pad and on reclamation area which appears to be landowner related, no approved variance in well file. See photos #8 -#9.		
Corrective Action:	Remove all unused equipment unless a variance per rule 606.a(2) is approved.		Date: 01/15/2024
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Metal mesh cage around weights and belts.		

Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Cattle panel enclosure around produced water tank, separator, meterhouse, and telemetry.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panel around wellhead and pumpjack.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Pipe bollards around cathodic protection.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Other	# 1		
Comment:	Lube oil container.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	On separator vent stack.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Natural gas motor.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead and block valve assembly.		
Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:	3" line from wellhead to separator. 1" line from separator to prime mover.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Telemetry, cathodic protection.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	PVC access		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	3" line from separator to meterhouse. Calibration date 7/24/2023.		

Corrective Action:		Date:	
--------------------	--	-------	--

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLs	PBV STEEL		37.224850,-107.551500	

Comment: Partially buried steel tank labeled 95 bbl.

Corrective Action:		Date:	
--------------------	--	-------	--

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	

Comment:

Corrective Action:		Date:	
--------------------	--	-------	--

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	272399	Type:	WELL	API Number:	067-08949	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	08/16/2023		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	0	Fluid Type:						
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			
Berms	Pass	Culverts	Pass	Material Handling And Spill Prevention	Pass	Container within containment.
Gravel	Pass					
Ditches	Pass	Ditches	Pass			

Comment: [Observed gulley erosion and sediment migration on south side fill slope. See photo #8.](#)Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 11/30/2023

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403597738	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6325199">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6325199</a>
712700884	INSPECTION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6325182">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6325182</a>