

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2023

Submitted Date:

11/16/2023

Document Number:

712700880**FIELD INSPECTION FORM**Loc ID 306913 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:22 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277489	WELL	PR	05/03/2005	CBM	067-09040	HUBERT MORRISON A 2	PR

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

Location			
Lease Road:			
Type	Access		
comment:	Access from CR 523. Private road, through residence. Gravel surface.		
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Content and volume label, NFPA placard on produced water tank.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Warning signs on pumpjack fencing. NFPA placards on separator and meterhouse.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Metal sign posted at location entrance.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	24 hour operator contact number and 911 local emergency number posted on well location signage.		
Corrective Action:			Date:
Good Housekeeping:			
Type	WEEDS		
Comment:	Observed musk thistle, now dead, along the entire south side of the location.		
Corrective Action:			Date:
Type	STORAGE OF SUPL		
Comment:	Observed a camper and plow truck stored on pad which appears to be landowner related, no approved variance in well file. See photo #3.		
Corrective Action:	Remove all unused equipment unless a variance per rule 606.a(2) is approved.		Date: 01/15/2024
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	T-posts and barbed wire along three sides of location.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Cattle panel enclosure around telemetry, meterhouse, separator, and produced water tank.		

Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Metal mesh cage around weights and belts.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panel around wellhead and pumpjack.		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:	3" line from wellhead to separator. 2" line from separator to produced water tank.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	PVC access		
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	Telemetry, electric control box, electric service panel, cathodic protection.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	3" line from separator to meterhouse. Calibration date 1/3/2023.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead and block valve assembly.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	On separator vent stack.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.217440,-107.555470	
Comment:	Partially buried steel tank labeled 95 bbl.					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	277489	Type:	WELL	API Number:	067-09040	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	04/18/2023		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	4	Fluid Type:						
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			
Berms	Pass	Culverts	Pass			
Ditches	Pass	Ditches	Pass			
Gravel	Pass					

Comment: No visible erosion or sediment migration observed during inspection.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403597602	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6325132
712700885	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6325128