

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/15/2023

Submitted Date:

11/16/2023

Document Number:

712700881

FIELD INSPECTION FORM

Loc ID 325508 Inspector Name: Pattillo, Curtis On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Findings:

- 24 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214912	WELL	PR	05/06/2022	CBM	067-06516	SITTON 01-13 1	PR

General Comment:

[SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.](#)

Location			
Lease Road:			
Type	Access		
comment:	Access from CR 526. Gravel surface.		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Content and volume label, NFPA placard on produced water tank.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Label on lube oil container.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Warning signs on pumpjack enclosure.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Metal sign posted at location entrance on telemetry fencing.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	24 hour operator contact number and 911 local emergency number posted on well location signage.		
Corrective Action:		Date:	
Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Observed agricultural and recreational equipment stored/not in use on pad and on reclamation area which appears to be landowner related, no approved variance in well file. See photos #2-#3.		
Corrective Action:	Remove all unused equipment unless a variance per rule 606.a(2) is approved.	Date:	01/15/2024
Type	OTHER		
Comment:	Observed impacted material on ground at prime mover muffler. See photos #8-#9		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and increase self-inspection intervals.	Date:	11/30/2023
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	Cattle panel enclosure around produced water tank, separator, and meterhouse.		

Corrective Action:		Date:	
Type	LOCATION		
Comment:	Wood posts and hog wire, T-posts and barbed wire on two sides of location.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Cattle panel around telemetry.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panel around wellhead assembly.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Metal mesh cage around weights and belts.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Lube oil container.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Natural gas motor		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Accessible		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	On separator vent stack.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead and block valve assembly.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Telemetry, cathodic protection.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS

PRODUCED WATER	1	<50 BBLs	PBV STEEL		37.218350,-107.583110
Comment: Partially buried steel tank labled 21 bbl.					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 214912 Type: WELL API Number: 067-06516 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 05/04/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Culverts	Pass	Material Handling And Spill Prevention	Pass	Container within containment.
Gravel	Pass					
Berms	Pass	Ditches	Pass			
Compaction	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403597627	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6325152
712700886	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6325130