

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/16/2023

Submitted Date:

11/16/2023

Document Number:

697008370

FIELD INSPECTION FORMLoc ID 330461 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

11 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430301	WELL	PR	10/01/2018	OW	123-36119	SHURVIEW 33C-3HZ	SI
430307	WELL	SI	09/01/2021	OW	123-36122	SHURVIEW 13N-3HZ	TA

General Comment:

LocationOverall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	x 2		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	TRASH		
Comment:	Miscellaneous trash on location and wellhead lease road, see attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	12/08/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panel x 2		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Livestock fencing		
Corrective Action:		Date:	

Equipment:

Type: Emission Control Device	# 3		corrective date
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	

Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 2		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	#		
Comment:	Automation array, solar array, Bradenhead gas combustor, ECD scrubbers, steel storage unit, temporary 500 bbls skid mount tank at wellheads		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Calibration card is current		
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:	Bradenhead valves are exposed at surface.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,	
Comment:	210 bbls, anchored.					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					
Date:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	8	300 BBLS	STEEL AST		,
Comment:					

Corrective Action:		Date:	
Paint			
Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			
Berms			
Type	Capacity	Permeability (Wall)	Permeability (Base)
Metal	Adequate	Walls Sufficient	Base Sufficient
Comment:			
Corrective Action:		Date:	
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 430301 Type: WELL API Number: 123-36119 Status: PR Insp. Status: SI**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 08/03/2023Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 34 Fluid Type: NoneEnd Surf Csg Pressure: --Comment: Corrective Action: Date: Facility ID: 430307 Type: WELL API Number: 123-36122 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: Comment: Offset mitigationCorrective Action: Date: **BradenHead**Date of Last Brhd Test: 09/19/2022Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 26 Fluid Type: WATER AND GASEnd Surf Csg Pressure: 1Comment: Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Fail			

Comment: [Heavy erosion on lease road to well pad, see attached photos.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 12/08/2023

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 11/16/2023 at approximately 09:15 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the Anadarko Shurview 13N-3HZ Pad location #330461 in Weld County, Colorado.</p> <p>While there, I observed miscellaneous trash on location and heavy erosion on the lease road. During this inspection the following possible compliance issues were observed: Rule 606. with a corrective action date of 12/8/2023 and Rule 1002.f.(2)C with a corrective action date of 12/8/2023.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	petersont	11/16/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403598503	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6325766
697008371	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6325760