

## Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RMV 25-20 Pad

Location # 335236



Photo # 7264 From entrance to location



Photo # 7265 Location

## Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RMV 25-20 Pad

Location # 335236



Nov 21, 2023 at 11:58:09 AM  
CO

Photo # 7266 Location



Nov 21, 2023 at 11:45:18 AM  
CO

Photo # 7267 Battery sign weathered & cracking



## Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RMV 25-20 Pad

Location # 335236



Photo # 7268 Location



Photo # 7269 Location



## Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RMV 25-20 Pad

Location # 335236



Nov 21, 2023 at 12:01:15 PM  
CO

Photo # 7270 Location



Nov 21, 2023 at 11:46:37 AM  
CO

Photo # 7271 Open ended load line

## Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RMV 25-20 Pad

Location # 335236




Photo # 7272 Tank label damaged & missing required information