

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2023

Submitted Date:

11/18/2023

Document Number:

708902272

**FIELD INSPECTION FORM**Loc ID 324144 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10550

Name of Operator: MUSTANG RESOURCES LLC

Address: PO BOX 13550

City: BAKERSFIELD State: CA Zip: 93389

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Mustang		nwelch@vaqueroenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259159	WELL	SI	04/01/2022	GW	045-07696	BURNS 9-35-6-94 W	SI

**General Comment:****CECMC Inspection Report Summary**On 11/15/2023 at approximately 13:01 hours, I, Compliance Specialist, Wayne Smelser  
Conducted an on-site inspection at MUSTANG RESOURCES LLC BURNS 9-35-6-94 W Pad.

Location # 324144 in Garfield County Colorado.

Location is within High Priority/Density/Black Bear Habitat areas &amp; in close proximity to NSO Habitat area.

Location is approximately 253 yards from Porcupine Creek.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Signs/Marker - Production tank not properly labeled/missing required information with a CA date of 12/18/2023
2. Equipment - Meter calibration info not conspicuously posted, no meter on location & no signage as to where meter is located with a CA date of 12/18/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	TANK LABELS/PLACARDS			
Comment:	Production tank not properly labeled/missing required information			
Corrective Action:	<p>All Tanks with a capacity of 10 Barrels or greater will be labeled or posted with the following information:</p> <p>A. Name of Operator;            B. Operator's emergency contact telephone number;            C. Tank capacity;            D. Tank contents; and            E. NFPA label or equivalent globally harmonized label.</p>			Date: 12/18/2023
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type	BATTERY			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911/1-888-291-8588			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No _____				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	LOCATION			
Comment:	Barbed wire			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Bird Protectors	# 1			corrective date
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 1			
Comment:				

Corrective Action:		Date:	
Type: Plunger Lift	# 0		
Comment:	Well not on plunger lift		
Corrective Action:		Date:	
Type: Gas Meter Run	# 0		
Comment:	Meter calibration info not conspicuously posted, no meter on location & no signage as to where meter is located.  Spoke with pumper & he said meter is located on the SAVAGE #11-35-6-94 W pad, location # 324139		
Corrective Action:	Post signage on the BURNS 9-35-6-94 W pad as to the location of the gas meter for the BURNS 9-35-6-94 W well.	Date:	12/18/2023
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible.  Last bradenhead test 8/15/2022		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	Marked		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	210
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
------	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	259159	Type:	WELL	API Number:	045-07696	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: _____									
Comment: <div>Shut In</div> <div>Well last produced December 2021</div>									
Corrective Action: _____ Date: _____									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Compaction				
Compaction						Light compaction in some areas
		Ditches				
		Gravel				Sparse in sections
Gravel						Sparse to none in some areas

Comment: Location appears to have some gravel throughout the location with light compaction. Places with sparse to no gravel are present on location. Sparse gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Please refer to Signs/Marker & Equipment for observed compliance issues.	smelserw	11/18/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403600695	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6327964">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6327964</a>
708902273	Inspection 708902272 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6327962">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6327962</a>
708902274	Inspection 708902272 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6327963">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6327963</a>